ALL SAFE INSPECTIONS 419.902.1308 stan@asitoledo.com https://asitoledo.com





RESIDENTIAL INSPECTION REPORT

930 Askin Street Maumee, OH 43537

> Stanley Jechura 01/30/2024



Inspector Stanley Jechura License #OHI.2019005315 419.902.1308 stan@asitoledo.com



Inspector Scott Jechura License #OHI.2019007467 419.902.1308 stan@asitoledo.com

1: INSPECTION DETAILS

Information

General Information: Scope	General Information: Stories	General Information: Square Feet
Full General Inspection	1	659 Sq Ft
General Information: Year Built	General Information: Bedrooms	General Information: Bathrooms
1949	2	1
General Information: Garage	General Information: Occupancy	General Information: Front Facing
Detached	Occupied, Furnished	West
		West

General Information: Introduction

Thank you for Choosing All Safe Inspections! We hope you found our services to be professional, thorough, and informative.

This report was prepared following a general home inspection which is a non-invasive evaluation of the visible and accessible major components of a home to assist with identifying areas that may require repairs or updates. The inspection was performed per the guidelines established in ASI's Standards of Practice and Ohio State Law.

Home inspectors are not experts in every system of the home but are trained to recognize conditions that may affect the safety or habitability of the dwelling, pose future damage concerns, or high dollar repairs. Any defects identified and conditions listed are based on the inspectors sole opinion and should be considered for further evaluation by a qualified and licensed trade-specific contractor. Your inspector may offer specific repair recommendations as a courtesy with no guarantee or warranty implied.

Home inspections are not technically exhaustive, for example, the inspector did not disassemble the furnace to examine internal components, did not inspect for local code violations, and did not report typical cosmetic wear.

How to read this report:

Maintenance or Low Priority concerns are items that do not affect the livability of the dwelling, do not pose safety or significant future damage concerns, and do not typically require immediate attention. Items in this category should be regularly monitored and maintained. Condition is usually listed as Very Good, or Acceptable.

Repairs Needed/Medium Priority concerns are considered significant and require further evaluation, troubleshooting and repair, or replacement. Condition is usually listed as Acceptable or Marginal.

Safety Concerns or High Priority concerns are items that present current safety , possible significant future damage concerns, or potential short term high dollar repairs. Condition is usually listed as Marginal or Poor.

Electrical Defects

Due to the potential of safety or fire hazards and the complexity of electrical systems, any defects should be considered for further evaluation and repair by a licensed electrical contractor. Minor concerns such as missing cover plates and fixture covers can typically be corrected by the homeowner but should still be considered a potential safety hazard and repaired in a safe and timely manner.

Printing (PDF) and Summary Version

To view and/or print a PDF copy of the full report or a summary version, click the icon located on the right side under the cover photo. To view a summary version of the report (concerns only), click the center icon under the cover photo.

Mobile Device View

When viewing on mobile devices, photos and defect categories may be condensed. Click or tap on the photo or defect box to expand it.

Repair Request Builder - Click the "Report Tools" button at the top of the report to access the repair request builder and copy/paste tools.

2: FOUNDATION & STRUCTURE

Information

Guttering and Grading : ConditionBasement: Construction TypeVery GoodBlock

Basement: Sump Pump Present **Basement: Perimeter Drain** Undetermined or Not Visible

Framing: Type - Wall Structure Wood

Attic(s): Condition
Very Good

Framing: Condition Acceptable Attic(s): Insulation Type

Fiberglass, Batt

Maintenance or Low Priority

Basement: Condition Acceptable

Framing: Type - Floor Structure Wood Joists, Steel Main Beams, Steel Posts

Attic(s): Framing Type Stick Framed

Attic(s): Viewed From Main Attic, Access Opening Only

Concerns, limitations, and recommendations

2.1.1 Guttering and Grading

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:

• Regular monitoring and maintenance.

2.2.1 Exterior Walls

DETERIORATED MORTAR JOINTS

Deteriorating mortar joints can lead to loose blocks or brickwork and settling.

Recommendations:

• Fill (tuck point) any deteriorated mortar joints to prevent worsening.



Maintenance or Low Priority



2.3.1 Basement **OBSTRUCTED**

Repairs Needed/Medium Priority

Portions of the basement were obstructed or inaccessible preventing adequate view.

Recommendations:

• Further evaluation when accessible.

Maintenance or Low Priority

Maintenance or Low Priority

Portions or all of the basement walls were covered with finished materials preventing view/evaluation of foundation walls.

Repaired cracks indicate past foundation damage or movement

Recommendations:

FINISHED AREA(S)

2.3.2 Basement

2.3.3 Basement

concerns.

CRACKS - REPAIRED

Recommendations:

-Monitor the finished areas for signs of moisture.



2.3.4 Basement LEANING OR BOWING -REPAIRED

damage or movement concerns.

Monitor for re-occurrence.


Repaired or re-supported walls indicate past significant foundation

Recommendations:

• Monitor for worsening.







2.3.5 Basement

SUMP PUMP OR CROCK -IMPROPER INSTALLATION

Improperly installed or temporary/emergency use type installation indicates possible possible past water intrusion concerns.

Recommendations:

• Properly install the sump pump.





VISIBLE PREVIOUS REPAIRS -ACCEPTABLE

Previously repaired or re-supported flooring indicates possible past damage or structural modification.

Recommendations:

• Monitor or further evaluate the affected area(s).

2.5.1 Attic(s)

LIMITED ACCESS

The attic was viewed from the access hatch only due to obstructions, lack of flooring, or location/size of opening.

Recommendations:

• Further evaluation when accessible.

Repairs Needed/Medium Priority

Maintenance or Low Priority

Maintenance or Low Priority



3: ROOFING & COMPONENTS

Information

Roof Coverings: Material Architectural Grade Shingles	Roof Coverings: Condition Very Good	Roof Co Methoo Grour
Roof Coverings - Type 2: Material Polycarbonate Panels	Roof Coverings - Type 2: Condition Very Good	Roof Co Inspect Grour
Penetrations & Flashings:	Penetrations & Flashings:	
Chimney Type(s)	Condition	
Brick, Parge Coated	Acceptable	

Roof Coverings: Inspection Method Ground, On Roof

Roof Coverings - Type 2: Inspection Method Ground, Ladder

Roof Coverings: Estimated Age

0-10 Years

Estimated age of roofing is provided as a courtesy to assist in determining remaining lifespan and is determined by the visible condition of the roof coverings at the time of inspection. -Architectural Grade Shingles - Typical lifespan - 30 years or more (depending on quality).

Roof Coverings - Type 2: Estimated Age

0-10 Years

Estimated age of roofing is provided as a courtesy to assist in determining remaining lifespan and is determined by the visible condition of the roof coverings at the time of inspection. -Metal or Composite Roofing - Typical lifespan - 50 years or more.

Concerns, limitations, and recommendations

3.1.1 Roof Coverings

NO CONCERNS NOTED

Maintenance or Low Priority

No significant damage or defects were observed at the time of inspection.

Recommendations:



3.2.1 Roof Coverings - Type 2 NO CONCERNS NOTED

Maintenance or Low Priority

Maintenance or Low Priority

No significant damage or defects were observed at the time of inspection.

Recommendations:

• Regular monitoring and maintenance.



3.3.1 Penetrations & Flashings

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:



4: EXTERIOR

Information

Siding, Eaves, & Flashings: Siding **Type/Condition** Vinyl **Decks, Balconies, & Porches: Types** Wood Deck

Walkways, Patios & Driveways:

Concrete, Pavers, Acceptable

Walkway Type/Condition

Type/Condition Aluminum Wrapped, Very Good

Siding, Eaves, & Flashings: Fascia

Decks, Balconies, & Porches: Condition Acceptable

Siding, Eaves, & Flashings: Soffits Type/Condition Vinyl, Vented

Walkways, Patios & Driveways: **Driveway Type/Condition** Asphalt, Marginal

Concerns, limitations, and recommendations

4.1.1 Siding, Eaves, & Flashings

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:

• Regular monitoring and maintenance.



4.2.1 Decks, Balconies, & Porches WORN/PEELING PAINT

Maintenance or Low Priority



Worn/peeling paint poses weathering concerns and a possible lead health hazard in homes built prior to 1978.

Recommendations:

Repaint as needed. •



4.2.2 Decks, Balconies, & Porches

EXPOSED WOOD

REAR ENTRY

Exposed wood poses excessive weathering and possible water damage concerns.

Recommendations -

• Seal any exposed wood surfaces to prevent excessive weathering.

4.3.1 Walkways, Patios & Driveways

ASPHALT - MODERATE TO SEVERE DAMAGE

DRIVEWAY

Moderate to severe cracking, settling, or deterioration was observed.

Recommendations:

• Fill any cracks/repair and re-seal as needed or consider replacement based on severity of concerns.



4.3.2 Walkways, Patios & Driveways

Repairs Needed/Medium Priority

Repairs Needed/Medium Priority

PAVERS - SETTLED, UNEVEN, OR DAMAGED

REAR WALKWAY

Settled or damaged pavers can pose a possible trip/fall safety hazard.



5: WINDOWS & DOORS

Information

Windows: Material Vinyl

Doors: Condition Acceptable Windows: Condition Acceptable Windows: Basement Windows Vinyl, Very Good

Concerns, limitations, and recommendations

5.1.1 Windows



Maintenance or Low Priority

OBSTRUCTED FRONT BEDROOM

One or more windows or doors were obstructed preventing full view/evaluation or testing.

Recommendations:

• Further evaluation/testing when accessible.



5.1.2 Windows

HARDWARE - DAMAGED OR MISSING

ALL WINDOWS

Missing tilt latch covers do not affect operation of windows.

Damaged or missing hardware such as lock latches, tilt latches, or cranks and operating mechanisms were observed preventing proper operation.

Recommendations:

• Replace any damaged or missing hardware.



5.1.3 Windows

INOPERABLE OR STUCK SASHES

LIVING ROOM - FRONT RIGHT WINDOW

One or more windows were inoperable, painted shut, or **stuck partially open** preventing proper operation.

Recommendations:

• Further evaluate and repair to functional use.



5.2.1 Doors

DAMAGED OR RUSTED

REAR ENTRY DOOR

Cracked jamb at closer.

Damaged or rusted doors were observed.

Recommendations:

• Repair or replace any affected doors as deemed appropriate.



Maintenance or Low Priority

5.2.2 Doors WEATHERSTRIPPING - DAMAGED OR MISSING

REAR ENTRY DOOR

Missing, inadequate or deteriorated weatherstrip poses excessive draft and energy loss concerns.

Recommendations:

• Replace any missing or worn weatherstrip to prevent energy loss.





6: INTERIOR

Information

Steps, Stairways & Railings: Condition Acceptable Walls/Ceilings: Condition Acceptable Floor Coverings: Condition Acceptable

Countertops & Cabinetry : Condition Acceptable

Concerns, limitations, and recommendations

6.1.1 Steps, Stairways & Railings

NO CONCERNS NOTED

Maintenance or Low Priority

Maintenance or Low Priority

No significant damage or defects were observed at the time of inspection.

Recommendations:

• Regular monitoring and and maintenance.



6.2.1 Walls/Ceilings

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:



6.3.1 Floor Coverings

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Maintenance or Low Priority

Maintenance or Low Priority

Recommendations:

• Regular monitoring and maintenance.

6.4.1 Countertops & Cabinetry

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:





7: PLUMBING

Information

Water Heater: Type Natural Gas

Water Heater: Manufacture Date Water Heater: Capacity 2008

Water Distribution & Fixtures: **Meter/Shut Off Location** Basement

Water Distribution & Fixtures: Condition Very Good

Gas Distribution System: Condition Acceptable

Water Heater: Condition Acceptable

40 gallons

Water Distribution & Fixtures: Main/Underground Supply Line Copper

Drain System: Type PVC, Cast-Iron

Gas Distribution System: Fuel Type Natural Gas

Water Heater: Manufacturer Richmond

Water Distribution & Fixtures: Source Public

Water Distribution & Fixtures: **Distribution Line Type** Copper

Drain System: Condition Acceptable

Gas Distribution System: Main valve location Gas Meter, Exterior

Concerns, limitations, and recommendations

7.1.1 Water Heater

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:

• Regular monitoring and maintenance.





7.2.1 Water Distribution & Fixtures

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:



7.3.1 Drain System

Loose toilets pose possible leaks and water damage concerns.

Recommendations:

- Replace the wax ring seal or flange as deemed necessary.
- Properly secure the toilet.

7.4.1 Gas Distribution System

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Maintenance or Low Priority

Recommendations:





8: ELECTRICAL

Information

Service Entry: Type
OverheadService Entry: Condition
AcceptableService Panels: Main PanelService Panels: Main PanelType/Condition
Circuit BreakerLocation
BasementOutlets, Switches & Fixtures:
Wiring TypeOutlets, Switches & Fixtures:
Condition

Acceptable

Service Panels: Main Amperage 100 AMP

Service Panels: Sub Panel(s) Garage

Outlets, Switches & Fixtures: GFCI Location(s)

Kitchen, Exterior, Bathrooms, Garage

GFCI (Ground Fault Circuit Interrupters) are designed to protect occupants from electrical hazards in the case of a short circuit and should be installed at all water prone areas.

Outlets, Switches & Fixtures: AFCI Location(s)

Not Present

Copper

AFCI (Arc Fault Circuit Interrupters) are designed to protect occupants from electrical hazards in the case of arcing electrical components indicating loose or worn wiring connections. Modern electrical standards recommend installation of AFCI breakers in all finished living areas.

Concerns, limitations, and recommendations

8.1.1 Service Entry

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:



Stanley Jechura

8.2.1 Service Panels MISSING BREAKER SLOT COVER(S)

MAIN PANEL

Missing breaker slot covers pose a possible safety hazard.

Recommendations:

• Replace any missing breaker slot covers.

8.3.1 Outlets, Switches & Fixtures

Repairs Needed/Medium Priority

🚺 Safety Concern or High Priority

OBSTRUCTED

LIVING ROOM AND BEDROOMS

Multiple outlets were obstructed or in use preventing testing.

Recommendations:

• Further evaluation and testing when accessible.





EXTENSION CORD IN PERMANENT USE

REAR PATIO/POND

Extension cords pose a potential electrical safety hazard.

Recommendations:

• Install appropriately located outlets.





8.3.3 Outlets, Switches & Fixtures EXPOSED WIRING AND/OR CONNECTIONS

Safety Concern or High Priority

ATTIC AND DRIVEWAY

Exposed wiring or connections pose a potential electrical safety hazard.

Recommendations:

• Install junction boxes at any exposed wiring connections or conduit at any exposed wiring.



9: HEATING & COOLING

Information

Heating: Furnace Type Forced Air

Heating: Manufacture Date 2017

Cooling: Brand Goodman

Fireplace: Type Gas, Free-Standing

Heating: AFUE Rating 90+% (High Efficiency) Heating: Fuel Type Natural Gas

Heating: Condition Acceptable

Cooling: Manufacture Date 2019

Fireplace: Condition Acceptable Heating: Brand Goodman

Cooling: Type Central Air Conditioner

Cooling: Condition Undetermined

AFUE (Annual fuel utilization efficiency) is a metric used to measure furnace efficiency in converting fuel to energy. A higher AFUE rating means greater energy efficiency. 90% or higher meets the Department of Energy's Energy Star program standard.

Maintenance or Low Priority

Concerns, limitations, and recommendations

9.1.1 Heating

CORROSION AT HEAT EXCHANGER - MINOR

Light corrosion was noted at the visible portion of the heat exchanger.

Recommendations:

- Monitoring for worsening.
- Further evaluation and repair as needed.



9.2.1 Cooling

LOW OUTSIDE AIR TEMPERATURE



Unit was winterized/covered.

Unable to test unit due to low outside air temperature (less than 60 degrees) at the time of inspection.

Recommendations:

• Further evaluation/testing when weather conditions permit.



9.3.1 Fireplace

NO CONCERNS NOTED

No significant defects or damage was observed at the time of inspection.

C

Maintenance or Low Priority

Recommendations:

• Regularly monitor and maintain.



10: APPLIANCES

Information

Smoke and CO Detectors: Condition Acceptable

Built in Microwave: General Information Condition - Acceptable

Clothes Dryer: General Information Condition - Acceptable, Type -Electric

Refrigerator: General Information Range: General Information Condition - Very Good Condition - Acceptable, Type -

Dishwasher: General Information Clothes Washer: General Condition - Very Good

Bathroom Exhaust Fan(s): **General Information** Condition - Acceptable

Gas

Information Condition - Acceptable

Concerns, limitations, and recommendations

10.2.1 Refrigerator **NONE NOTED**

All tested appliances operated normally.





11: DETACHED STRUCTURES

Information

General: Structure/Type Garage - 3 Car

Chimney: Type/Condition Metal

Floor Slab: Condition Marginal

Roofing: Material/Age Architectural Grade Shingles

Chimney: Condition Acceptable

Siding, Eaves, & Flashings: Siding Type/Condition Vinyl, Very Good

Siding, Eaves, & Flashings: Soffits Framing: Condition **Type/Condition** Vinyl, Very Good

Doors and Windows: Automatic Door Opener Present

Acceptable

Heating System: Type Gas

Roofing: Condition Very Good

Gutter System and Grading : Condition Acceptable

Siding, Eaves, & Flashings: Fascia Type/Condition Vinyl, Very Good

Doors and Windows: Condition Acceptable

Heating System: Condition Marginal

Concerns, limitations, and recommendations

11.1.1 General

ACCEPTABLE OVERALL CONDITION

Repairs Needed/Medium Priority

Maintenance or Low Priority

Typical medium and/or low priority concerns were observed at the time of inspection.

Recommendations:

- Complete any needed repairs. •
- Regular monitoring and maintenance.



11.4.1 Gutter System and Grading

GUTTERS - DAMAGED, **MISSING, OR INADEQUATE**

Dented front gutter does not affect operation.

Damaged, missing, or inadequate gutters pose foundation water intrusion and movement concerns or hidden damage such as rotted fascia boards and water intrusion in walls.

Recommendations:

 Repair or replace the guttering as needed to ensure adequate rainwater dispersion away from the foundation and dwelling.



CRACKED OR SHIFTED FLOOR SLAB

Cracks in the floor slab are typical and do not generally affect the structural integrity of the foundation.

Larger cracks or settling indicates past or possible excessive foundation movement due to oversaturated exterior grading.

Recommendations:

- Fill any cracks with an appropriate sealant and monitor for re-occurrence or worsening.
- Correct any guttering or exterior grading concerns.
- Consult a qualified contractor for further evaluation and repair of larger cracks or excessive settling.



Repairs Needed/Medium Priority

11.6.1 Siding, Eaves, & Flashings

NO CONCERNS NOTED

No significant damage or defects were observed at the time of inspection.

Recommendations:

• Regular monitoring and maintenance.

11.7.1 Framing

OBSTRUCTED OR LIMITED VIEW

All or portions of the framing were covered or obstructed preventing full view or evaluation.

Recommendations:

• Further evaluation when accessible.



Maintenance or Low Priority



11.8.1 Doors and Windows

AUTO REVERSE SENSOR -FAULTY OR MISSING

LEFT OVERHEAD DOOR.

The auto reverse safety sensors were missing or not operating properly when tested.

Safety Concern or High Priority

Safety Concern or High Priority

Recommendations:

• Further evaluation and and repair.



11.9.1 Heating System

INADEQUATE CLEARANCE

Propane tank next to furnace.

Combustible materials were noted in close proximity to the fireplace posing a possible fire safety hazard.

Recommendations:

• Clear any combustible items from near the fireplace.

